

P.O. Box 925  
8 Heritage Park Road  
Clinton, CT 06413  
Tel: 860-664-4906  
Fax: 860-664-4907

[www.cookwithkenyon.com](http://www.cookwithkenyon.com)  
[customercare@cookwithkenyon.com](mailto:customercare@cookwithkenyon.com)

Below is a list of services performed during an overhaul of a KENYON Pressurized Alcohol Stove. In an overhaul of your stove, we will:

- Rebuild both alcohol burners using all new parts
- Replace the check valve inside the alcohol tank
- Replace the U-cup on the pump assembly
- Replace the gasket on the fill cap
- Give the stove and burners a complete and thorough cleaning
- Replace all labels and test both burners

Parts for Models #205 and #126 are very limited or are no longer available. A complete overhaul cannot be performed on either model.)

This overhaul also applies to **KENYON** Combination Alcohol/Electric Stoves. The electric burners will be tested to ensure they are in proper working order. If repairs are needed to the electric portion of the combination stove, additional charges will apply.

The cost of a complete overhaul service is as follows depending on the type of stove:

- |                                   |          |                          |
|-----------------------------------|----------|--------------------------|
| • Single Burner, Alcohol Only     | \$159.00 | plus tax, if applicable* |
| • Single Burner, Alcohol/Electric | \$179.00 |                          |
| • Two Burner, Alcohol Only        | \$239.00 |                          |
| • Two Burner, Alcohol/Electric    | \$259.00 |                          |

The above prices include return ground freight charges to the continental US. Any additional services will be pre-approved by the customer and will be in addition to the above pricing.

Due to the age and availability of various parts, this overhaul cannot be performed on models with ovens or propane/kerosene burners. If you are interested in parts for these models, please contact Customer Service at (860) 664-4906 or by fax at (860) 664-4907.

Please read the following instructions on shipping your stove.

- Use care when packaging your stove for shipment to our facility. Pay close attention to the corners of the stove.
- Please **DO NOT** use Styrofoam peanuts as they get stuck inside the stove body.
- Verify that the tank is empty of all alcohol.
- Please enclose a note with name, address and daytime phone number and that you are requesting an overhaul service on your stove.

Thank you for your interest in KENYON and I hope you will allow us to be of service to you in the future.

Regards,  
Customer Service Department

\*Residents of CT and FL please include your local state tax.